Hi Cocob,

Yes, thats the Reason.
But the path is already in the BuildMethod Discription.
I will attach the file to this Message.
I Think, their are some problems with the Environment of the Program.
There is no effect after changing the Path to the Headerfiles.
Have i adapt any other File to recognize the Pathes?
I have added the Log to the file so the Message is mor readable

Dieter

File Attachments
1) GCC_ARM.bm, downloaded 539 times